



Boring: 4000

Datum: 20-11-2017



Boring: 4001


Datum: 20-11-2017



Boring: 4002

Datum: 20-11-2017


Opmerking: GWS niet herkenbaar



Boring: 4003


Datum: 20-11-2017

GWS: 130




Boring: 4004

Datum: 20-11-2017
GWS: 150



Boring: 4005

Datum: 20-11-2017




Boring: 4006

Datum: 20-11-2017

Opmerking:

GWS niet duidelijk



Boring: 4007

Datum: 20-11-2017

