

Boring 2018H153_2

Kopgegevens 2018H153_2

KPC	KBN	KBS	KDT	KDB	KWO	KL	KBT	KED	KGW	KXC	KYC	KPL	KCS	KMV	KPZ	KRV	KBM	KPV	KGM	KUV	KOM	
2018H153	2	PP	21-08-2018	LB	H	GR	H	275		191987.968	235353.38	5	31370	31.18	4	TAW	MDGP	BAN	Ravels	BAAC	Vlaanderen	GWT niet bereikt

Laaggegevens 2018H153_2

GBG	GAB	GOG	GAO	GRM	GBT	GKL	GKM	GVO	LTK	LZT	LZS	BBB	LSL1	LSL2	LVS	BBH	BBI	LTB	LGK	LGB	LBH	LPR	LBG	LSR	LCA	BFM	BOR	BBR	BBV	AHK	ARL	AAW	AOB	AVB	AVS	APA	APO	AFO	AOV1	AOV2	AOV3	AAI	LOM									
0		10	DU		E7	BRGR		D	Z	Z4	SMG					Ap	OP					h1	WO3		1		O																									
10	DU	40	SA		E7	LBRGR		D	Z	Z4	SMG					Ap	OP					h1	WO2		1		O																									
40	SA	60	SA		E7	BR		D	Z	Z4	SMK					Apb						h2	WO2		1		O																									
60	SA	100	DU		E7	GE		D	Z	Z4	SZK					C									1		O																									
100	DU	145	SA		E7	LGEWI		D	Z	Z4	SZK					Cg									1	FE2	O																									
145	SA	200	SA		E7	GE		D	Z	Z4	SZK					Cg									1	FE1	O																									
200	SA	210	SA		E7	ORWI		V	Z	Z4	SZG					Cg									1	FE1	OR																					lokaal fijner of grover				
210	SA	220	SA		E7	OR		V	Z	Z4	SMG					Cg									1	FE3	OR																									
220	SA	245	SA		E7	ORWI		V	Z	Z4	SZG					Cg									1	FE3	OR																						bijmenging fijn, lemig zand			
245	SA	260	SA		E7	GE		V	Z	Z4	SZK					Cg							g1		1	FE1	O																									
260	SA	270	SA		E7	WIOR		V	Z	Z4	SZK					Cg								g2		1	FE3	OR																							zanden van Lomme!?	
270	SA	275			E7	GNOR		V	L	Z3	SZG					Cg									1	FE3	OR																									mogelijk brokken zware zandleem aanwezig

Boring 2018H153_4

Kopgegevens 2018H153_4

KPC	KBN	KBS	KDT	KDB	KWO	KL	KBT	KED	KGW	KXC	KYC	KPL	KCS	KMV	KPZ	KRV	KBM	KPV	KGM	KUV	KOM
2018H153	4	PP	21-08-2018	LB	H	OV	H	150	192029.954	235406.658	5	31370	31.07	4	TAW	MDGP	BAN	Ravels	BAAC	Vlaanderen	GWT niet bereikt; onverhaard staalvloer

Laaggegevens 2018H153_4

GBG	GAB	GOG	GAO	GRM	GBT	GKL	GKM	GVO	LTK	LZT	LZS	BBB	LSL1	LSL2	LVS	BBH	BBI	LTB	LGK	LGB	LBH	LPR	LBG	LSR	LCA	BFM	BOR	BBR	BBV	AHK	ARL	AAW	AOB	AVB	AVS	APA	APO	AFO	AOV1	AOV2	AOV3	AAI	LOM			
0		20	DU		E7	BRGE		D	Z	Z4	SZK	ZHB				Ap								1		O																				
20	DU	35	DU		E7	DGE		D	Z	Z4	SZK					AC								1		O																				
35	DU	80	GE		E7	GE		D	Z	Z4	SZK					C								1		O																				
80	GE	150			E7	GE		D	Z	Z4	SZK					Cg								1	FE1	O																				zeer weinig ijzervlekken

Boring 2018H153_7

Kopgegevens 2018H153_7

KPC	KBN	KBS	KDT	KDB	KWO	KL	KBT	KED	KGW	KXC	KYC	KPL	KCS	KMV	KPZ	KRV	KBM	KPV	KGM	KUV	KOM
2018H153	7	PP	21-08-2018	LB	H	GR	H	165		192078.121	235488.007	5	31370	30.6	4	TAW	MDGP	BAN	Ravels	BAAC Vlaanderen	GWT niet bereikt

Laaggegevens 2018H153_7

GBG	GAB	GOG	GAO	GRM	GBT	GKL	GKM	GVO	LTK	LZT	LZS	BBB	LSL1	LSL2	LVS	BBH	BBI	LTB	LGK	LGB	LBH	LPR	LBG	LSR	LCA	BFM	BOR	BBR	BBV	AHK	ARL	AAW	AOB	AVB	AVS	APA	APO	AFO	AOV1	AOV2	AOV3	AAI	LOM					
0		40	SA		E7	DBRGR		D	Z	Z4	SZK	ZHB				Ap	OP					h2	WO2		1		O																		zeer weinig kleine brokken humus en moedermateriaal los			
40	SA	50	SA		E7	GRBR		D	Z	Z4	SMK					Apb						h1	WO1		1		O																					
50	SA	70	SA		E7	GE		D	Z	Z4	SZK					C									1		O																					
70	SA	85	DU		E7	ORLGE		D	Z	Z4	SZK	ZL1du				Cg									1		O																				duidelijke sublagen kleiig, geoxideerd, oranje, matig grof (Z5) zand	
85	DU	115	GE		E7	LGE		D	Z	Z4	SZK					C									1		O																					
115	GE	130	SA		E7	GE		D	Z	Z4	SZK					Cg									1	FE2	O																					
130	SA	140	DU		E7	GEWI		D	Z	Z4	SZK					Cg									1	FE2	O																					
140	GE	160			E7	WI		D	Z	Z4	SZK					C							WO1		1		O																					sterk vervallen wortels